Installation procedure for Hercules Scan@home Touch 1248 USB scanner under Windows XP (version 4.02)

Once the driver has been installed, switch off the computer, connect the scanner and then reboot the computer.

- Right click on **MY COMPUTER** icon on your desktop and select **Properties**

- From the **Hardware** tab, and click on **Driver signing**.

- Select the option **Ignore-Install the software anyway and don't ask for my approval**. Click on **OK**.

- Still in **Hardware,** click on **Device Manager**.

- Under **Imaging devices**, right-click on **FlatbedScanner_21 #2**, and choose **Update Drivers**.

- First select **Install from a list or specific location (Advanced)**,

- Then, select **Do not Search, I will choose the driver to install**,

At this point, Windows should indicate the compatible divers available. Obviously, select the one appropriate for your model (**Scan@home Touch)**. Click on **Finish** to complete the scanner's installation.

You can check whether your scanner has been correctly installed by accessing the scanner's properties in **Device Manager** (right-click on **FlatbedScanner_21 #2**, and choose **Properties**)

If **Microsoft** is displayed next to **Driver provider**, the scanner has not been correctly installed.

You will know that the scanner has been correctly installed when the **Unknown** is displayed next to **Driver Provider**.