Why is my 3D Prophet 9700 detected as a 3D Prophet 9700Pro with Hercules and ATI drivers?

Few boards have been flashed during production with a bad PCI Identifier in their VGA bios. This means that ATI and Hercules drivers detect those boards as Radeon 9700Pro instead of Radeon 9700.

All our testing have proved that those boards run perfectly, exactly as the 3D Prophet 9700 boards, with same performances and same reliability.

All the other parameters – including core and memory clocks – are correct. So there is no need to reflash the board.