The scanner is connected correctly but has not been detected by the computer.

- Make sure that the scanner is switched on.
- Verify the connection between the scanner and the computer.

- Connect the scanner to the other USB port on your computer. Avoid using a USB hub as certain hubs do not control all USB devices.

- If the problem continues, test the scanner on a different computer.