

The TV output is not detected after installing the latest Nvidia drivers on my 3D Prophet III Ti 500. Why?

This problem is present with recent display driver releases. This is due to a bad TV encoder detection.

This problem has been resolved with the release of a new bios update, available in the [download section](#)