

When I try to connect with my Nintendo DS or DS Lite, the connection fails with error code 52000 or 52100. What should I do?

This problem occurs with Version 1.3 of the Hercules WiFi USB Transmitter drivers.

To resolve the problem, update to Version 1.5 of the drivers, currently available on the Hercules Technical Support website.