

Temporary fix to gain access to DJConsole Rmx2 control panel under OS X 10.9 Mavericks.

Upon the first installation of the current DJ driver package (**v4.69**) under OS X 10.9, the Rmx2 control panel is not accessible (appears as if the console was not connected).

A future package (currently being tested) will address this problem, but in the meantime, you can access the control panel with this simple procedure:

- Open **Audio/MIDI SETUP** (in **Applications >Utilities**).
- Under **Window > Show MIDI Window**, you should notice a component called USB MIDI Device.



- Turn **Off** the console. The icon should then be displayed as inactive:



- Click on the icon to select it, then click **Remove Device**. The icon should disappear.
- Close **Audio MIDI Setup**, and turn **On** the Rmx2. The control panel should now be accessible.